


Magnet Guidelines

Indicate desired cut line with a 100% magenta vector path. Include at least 1/8" white space or bleed.

NOTE: Cut line edges must be rounded to a 3/16" circle or larger. Tighter corners and sharp edges will not cut consistently and may need to be edited.

Use the 3/16" circle below to check all cut edges and corners, including any interior cutouts.

3/16 Diameter
Test Circle



GOOD: All cut edges pass the 3/16" circle test




BAD: Sharp corners and interior cutouts smaller than 3/16" will not be possible



GOOD: All cut edges pass the 3/16" circle test

GOOD: Interior cutouts are large enough

GOOD: Art includes adequate white space



BAD: Not enough white space/bleed may cause art to touch the edge or be cut off

BAD: Sharp corners and interior cutouts smaller than 3/16" will not be possible



GOOD: All cut edges pass the 3/16" circle test

GOOD: Art includes adequate white space



BAD: Not enough white space/bleed may cause art to touch the edge or be cut off

BAD: Sharp corners and interior cutouts smaller than 3/16" will not be possible

Import your artwork and use a magenta path to indicate the desired cut line.

Add at least 1/8" white space or bleed.

Sharp corners and curves tighter than the edge of a 3/16" circle are not recommended.

All edges should be smooth and rounded for consistent cutting and easy peeling.



3/16 Diameter
Test Circle



Magenta
Cut Line



1/8"



1/8" White Border

Cut Line

Width (2") x Height (2") = Area (4 square inches)